



View of the V-cut from the top.



Digging out the V-cut, looking towards the brickwork viewing area.



View of the V-cut from the junction of the track to the fossil area. The main access track to the reserve is to the left.



View of the V-cut from the extension track.



Putting in the clay lifts. The visible bricks area against the water.



Majority of the upper slope is cleared. Trees were also cleared last week.



View of the cleared slope looking down to the bird hide.



View of the slip viewed from the V-cut.



View of the works from the extension track.



Panorama of the works proceeding.



Some birds seem undeterred by the heavy machinery - cormorant.



Nature reserve extension area remains unchanged.